
Chapter 2: CNC Fundamentals & Vocabulary

CNC

Learning objectives

- **The Cartesian Coordinate System**
- **Motion Direction of CNC Mill and Lathe**
- **Types of Coordinate System**
- **Dimensioning Theory**
- **CNC Vocabulary**

Axis and Motion Nomenclature

CNC Machine Operations

- **Different CNC Machine tools may exhibit different machine motions**
 - **A typical 3-axis CNC Gantry Machine**
 - Moves above the stationary work piece (part)
 - Spindle moves at 90° in/out of the part
 - **A typical CNC lathe machine tool**
 - Slides along the part
 - **Multi-axis CNC Machines**
 - Rotary motion of spindle
 - **Stationary CNC machine, but tool is allowed to move in different direction**
- **Different CNC Machine tools use the same coordinate system**
- **Modeling a CNC Machine operation:**
 - **Calculate the tool movement relative to the coordinate system of the stationary part**

Axis and Motion Nomenclature


Cartesian System

- Machine coordinate system is described based on Cartesian system
 - X, Y, Z are at 90°
- Cartesian System
 - Use Right-hand Rule to designate the **primary axis** of the machine tool
 - The spindle

3-Axis and Motion Nomenclature

Right-Hand Rule of Coordinates


- Hold the thumb, forefinger and middle finger at 90° to each other
 - Thumb (X-axis), Forefinger (Y-axis) and Middle finger (Z-axis)
 - Each finger points to +ve direction of motion of the CNC tool
 - 3-axis Milling Machine:
 - The +Z-axis points into the spindle



3-Axis CNC Milling Machine

Direction of Spindle Movement


- The longest travel slide represents the X-axis
 - Each finger points to +ve direction of motion of the CNC tool
 - The +Z-axis points into the spindle



Multi-axis CNC Machine


Rotary Motion of Spindle

- **Positive (Clock-wise) of Spindle**
 - ❑ **Curl right-hand with thumb pointing out in +ve X, Y or Z axis direction**
 - ❑ **The curl of the finger represents the +ve rotation about each axis**




CNC Milling Machines

Examples



Typical CNC lathe



Horizontal Milling Machine
with multi-axis rotary table

CNC Milling Fundamentals

Cartesian Graph for CNC

Assume the 3-D frame of reference

- Reference Point (i.e., Origin): (X0, Y0, Z0)
- Ideally, the tool can move in any of the quadrants
- Coordinate at any time is designated in one of two ways:
- **Absolute Coordinate System:**
 - Calculate the distance relative to the origin (X0, Y0, Z0)
- **Incremental Coordinate System**
 - Calculate the distance relative to the last point
- **All CNC Machine Tools require a reference point to calculate the coordinates**

Options for Determine the Reference Point?

- Choose the point on the actual machine (MRZ)
- **Choose the point on the part - Point Reference Zero (PRZ)**


CNC Machine Reference Point

Point Reference Zero

Assume the reference point (PRZ) is located at:

- Lower Left-Hand Corner of the Part and
- On top of the Part

Hence **negative** Z-depths are below the surface of the machine



CNC Milling Fundamentals

Absolute Coordinates For Milling

Use the Origin as Reference point

- All points on the part, in the Cartesian graph, are plotted by measuring the (X, Y) distance and Z, if applicable, from the origin
- Coordinates of a point are represented as:
 - $(X(+)(-)p, Y(+)(-)q, Z(+)(-)r)$ Where p, q, r represent the distance along the respective axis
 - $(X3.25, Y-7.5, Z-0.5)$ Note the '+' sign is optional
 - Point is located:
 - 3.25 units along the +X axis
 - 7.5 units along the negative Y axis
 - 0.5 units along the negative Z-axis

Refer to more examples of Absolute Coordinates in Figures 2.11 and 2.12

CNC Milling Fundamentals

Incremental Coordinates For Milling

Use the **present position as reference point for the next movement**

- All points on the part, in the Cartesian graph, are plotted by measuring the (X, Y) distance between the current point and a known point
 - The first point usually starts from the origin

Using figure 2.13, given reference point 1 (1,3) find the incremental coordinates for:


- Point 2 from the previous point 1
- Point 3 from the previous point 2
- Point 4 from the previous point 3
- Point 5 from the previous point 4
- Point 6 from the previous point 5
- Point 7 from the previous point 6

CNC Turning Fundamentals

Cartesian Graph for CNC

In CNC Turning, we have:

- A Primary (horizontal) axis labeled Z
 - On a lathes the z-axis always runs through the spindle
 - Hence part is symmetrical around the Z axis
- Secondary (vertical) axis labeled X
 - The X-axis is perpendicular to the Z axis
- Use the XZ Cartesian Coordinate System to plot the points
 - Assume the origin is located on the RHS of the part
- Start all measurements with origin as reference point
- Because of symmetry only top part above Z axis required
 - No need to use all 4 quadrants




CNC Turning Fundamentals

Diameter Vs. Radius Programming

Consider a work piece of diameter
(along X Axis) 5 units:

- CNCez Diameter Programming Option:
 - To command an absolute move to the outside of part, you would program:
 - X5.0
- CNCez Radius Programming Option:
 - To command an absolute move to the outside of part, you would program:
 - X2.5



CNC Turning Fundamentals

Absolute Coordinates For Turning

Steps to plot a point (X,Y)

1. Start at Origin (X0, Z0)
2. Travel along the left/right of Z axis until you are below/above the target point
 - Write down the Z value
3. Go up/down to the target point in the X direction
 - Write down the X value


CNC Turning Fundamentals

Finding Absolute Coordinates

Consider a work piece of diameter
(along X Axis) 5 units:

Find point A:

1. Start at Origin (X0, Z0)
 2. Travel along the right of Z axis until you are below A
 - Write down the Z value (4)
 3. Go up to the target point in the X direction
 - Write down the X value (5)
- Radial XZ coordinates are (X5.0, Z4.0)
 - Diametrical XZ coordinates are (X10.0, Z4.0)



CNC Turning Fundamentals

Finding Incremental Coordinates

Consider a work piece of diameter
(along X Axis) 5 units:

Find point A:

1. Start at Origin (X0, Z0)
2. Travel along the right of Z axis until you are below A
 - Write down the Z value (4)
3. Go up to the target point in the X direction
 - Write down the X value (5)

- Radial XZ coordinates are (X5.0, Z4.0)
- Diametrical XZ coordinates are (X10.0, Z4.0)

Next Find Point B starting from A

